



Broker: Carlos Herrera
Tel: +52 (998) 235 4485
Email: c.herrera@yachtcancun.com



Beneteau 34 (2012)

Ubicado en Coconut Grove, Florida, EUA.

Detalles

Recent Services:

Engine Services Completed Both Engines (Oct 2022 at 500 hours) New Impellers, New V-Belt, (Maintenance on the Heat Exchanger (Intercooler), After Cooler (Air Cooler), DPS New Seals and New Oil, New Coolant, New Oil Filters, New Primary Fuel Filters, New Secondary Fuel Filters, Oil Change Engine.

Oil Change With Oil Filters and Fuel Filters on Generator (Oct 2022)

Tank fuel Polishing (Oct 2022)

NEW Antifouling With Anodes, Prospeed and LightSpeed (Jun 2022)

Maintenance in the Air Conditioning System (Sept 2022)

NEW Grill 110V (Oct 2022)

NEW 3 x Underwater SeablazeX2 Spectrum (Sept 2022)

NEW Simrad NSS12 EVO 3 (Sept 2022)

NEW Stereo Fusion RA210 (Sept 2022)

NEW Upholstery (Jun 2022)

NEW Lights Engine Room (Sept 2022)

NEW Step SeaDeck Engine Room (Oct 2022)

6 x 7.7" 2 x 6.5" Speaker JL Audio

NEW 2 x JL Audio Amplifier (Oct 2022)

Eslora:34ft

Manga:11.1ft

Calado:2.9ft

Motores:2012 Volvo D3-200 (500 hrs)

Tanque de combustible:129gal

Tanque de agua:42gal

Camarotes:1 (2 pax)

Baños:1

Ubicación:32

Exteriores





Interiores



